


COPY

LLOYD'S REGISTER OF SHIPPING



/P.

NEWCASTLE-ON-TYNE, No. 118463

Port

NEWCASTLE UPON TYNE.

17th November, 1961.

This is to Certify that I have

surveyed the Machinery of the Motor Tanker "BRITISH DUKE", 8562 tons gross of London, whilst afloat or in drydock at Brigham & Cowans' Yard, South Shields, from 27th October, 1961 to 17th November, 1961, for Docking, Auxiliary Boiler Survey, Part Continuous Survey of Engines, General Examination, Special examination and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

A.B.S. 11.61,

and that her Machinery Classification Record be continued in the Book.

subject to the electric wiring in way of both catwalks being again specially examined and dealt with as necessary at the next Special Survey.

Parts now examined:

(C.S. Items only)

Propeller and outside fastenings.

Main engine No. 1 side and centre crankpins and bearings.

Main engine driven scavenge pump cylinder, covers, piston and rod and salt water cooling pump. Main engine running. Independent fresh water cooling, lube and lub. oil circ. pumps. After independent air compressor and engine. Upper main air receiver. Separate oil fuel tanks. Evaporator. Steering machinery. Windlass. Ford inboard dynamo engine. Auxiliary electric equipment.

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OC) Tailshaft Survey—Oil Gland

C. N. THOMAS.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."