

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Port Helsinki.

7th of July, 1954.

This is to Certify *that I have*

in "SUCANIE" afloat and in floating dock at

15.6.54. whereby repair was effected to

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and I have Recommended that she be continued classed

record of docking 6.54. subject to the pipe for

No. 2 double bottom tank being length-

with the strongest top tanks being brought to comply with the most possible.

being fit to carry day and night cargo.

A. W. Wilson

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member of, or the Surveyors, or other Officers or Agents of the Society.

ft. B.) 20m.11.50.

(MADE AND PRINTED IN ENGLAND.)

002743-002749-0121

Lloyd's Register Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.