



COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

4th Floor Shurdut Bldg., Intramuros, Manila, Philippines

Telegrams: REGISTER, Manila
P. O. Box 1447Telephone: 330-90
3-15-78

January 14 1960

Messrs. Madrigal Shipping Co. Inc.,
6th Floor, Madrigal Building,
Manila.Attention: Mr. Moises J. Lopez

Dear Sirs,

S.S. "CERES"

With reference to your letter of the 14th August, 1959, relative to the drydocking and boiler and screwshaft surveys due on the above vessel, I am today in receipt of a communication from London stating that a Boiler Survey was carried out at Honolulu, Hawaii in October last, and that the vessel's Class was continued subject to the boilers being further examined on arrival in Japan.

I should be grateful to learn as soon as possible what action has been taken in this regard in order that I may advise London accordingly.

Yours faithfully,

E. R. SANDERSON
Surveyor to Lloyd's Register
of Shipping

© 2020

002750-002753-0108

Lloyd's Register
Foundation