


COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port CALCUTTA

19th May, 1959.

This is to Certify that

R. McINTOSH.

the undersigned Surveyor to this Society did at the request of

The Owners Representative survey the S.S. "JALAKRISHNA" 4991 tons gross of Bombay on the 29th April 1959 ~~and subsequently~~ whilst the ship was afloat at Calcutta for the purpose of ascertaining the nature and extent of damage stated to have been caused by bore tides in the River Hooghly on 26th April 1959 while the ship was lying at 3 Esplanade Moorings, Calcutta.

For further particulars see Log Books.

The undersigned upon examination

FOUND

One 15 fathom length of
1.7/8" special quality
stud link steel cable
broken and several links
strained, distorted.

RECOMMENDED

Cable be renewed.

The above recommendations have been made in order to place the ship in as good a condition as she was in before the alleged casualty, and have been deferred until new cable is available.

Fees - 50/-

SURVEYOR TO LLOYDS REGISTER OF SHIPPING.

icate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
the Committees of the Society use their best endeavours to ensure that the functions of the Society are
ecuted, it is to be understood that neither the Society nor any Member of any of its Committees is under
stances whatever to be held responsible for any inaccuracy in any report or certificate issued by the
its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of
default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers
of the Society."