

MONTREAL OFFICE

FAIRMOUNT

Report No.

Mtl. 13462

e of Survey:-

Part MBS

e:

Vessel laid up.

Following remains to complete the survey:-
complete Boiler Survey.

Safety valves to be adjusted under steam

Recommendations:-

The Vessel appears eligible to remain as classed ^{with} ~~without~~ fresh record of MBS 2,60 when the Survey is complete, as above.

002762-002764-0032



June 11th, 1960

© 2021

Lloyd's Register
Foundation