

fees paid

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel Sc.M.S. "NEDERLAND" Rpt. _____ Rot _____ No. 25678

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 15640 Depth "d" -

2nd Long. No. 42780 Proportions = $\frac{L}{D}$ 13.52

Framing as approved Sheerstrake as approved.

The is generally a sister ship to the "RAPANA"

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~100A1~~ "Carrying Petroleum in Bulk"

1 Dk. 2nd Dk. clear of Cargo Tanks, "Longitudinal Framing at bottom and at deck"

Cell. DBuE 69' 146t. DTf 25' 263t, FPT 134t, APT 80t.

F.K., 16 BH, Lloyd's A & CP.

P 93' B 47' F 48'

Machy Aft.

O.L. 483.25'

[Handwritten signatures]

15.6.37



© 2021

Lloyd's Register

002762-002769 Foundation