

Co-efficient of fineness.....

Any modification necessary }  
[Para. 4 (a) to (e)]\* }

C.D.B

Correction for 100, .....  
× Difference divided by 10 .....  
If 1/10ths length covered divide by 2

TELEPHONE: CENTRAL 5281 & 5282.




# Lloyd's Register of Shipping.

201, Tower Building.

Liverpool, 8th May, 1929.

Enclosure.



Dear Sir,

I beg to return herewith Liverpool Freeboard Report No.95320 on the motorship "THURLAND CASTLE", the particulars required having been filled in by the Surveyor.

I am, Dear Sir,


Yours faithfully,

*D. M. Keith.*

Secretary to the  
Liverpool Committee.

A.Scott, Esq.,

LONDON.



© 2021

Lloyd's Register  
Foundation

002762-002769-0162

Winter North Atlantic Line

\* If the frames, skin planking, or ceiling are of unusual thickness the breadth of vessel to inside of ceiling should be reported if possible.  
of ceiling should be reported if possible.  
of ceiling should be reported if possible.

+ State dimensions of freeing port area on back of this form.

¶ The Surveyor should state whether the fall in sheer as reported is measured  
at the water line.



9 MAY 1929

-9 MAY 1929

Rise in Shear  
from amidships  
[Para. 18 (e)]

gradual mean Sheer  
standard mean Sheer  
If limited as Para.

Heer } Stem.....  
at } Sternpost ...

Any modification neces-  
[Para. 4 (a) to (e)]<sup>\*</sup>  
do-efficient as corrected

© 2021

sheer at  $\frac{1}{3}$  of  
 gradual mean  
 standard mean  
 If limited