

WRECK SECTION No. 699

Steel Screw Steamer "ROSINA TOPIC"; No. 32741 in the Register Book; 3038 tons gross; Built in 1901-2 mo; Port of Registry, Susak.

Owners:- Slobodna Plovidba Topic D.D.

Classed:- +100A1 6,28 s.s.2ndNo.3-2,26 +LMC 2,26 BS 2,30 TS 11,29 NEB 13

WRECK SECTION No.

NT. TRIES O. O. AMSHIP UNKER C. BUNKER ASIATIC P. AGE O-BAXON P. JURK. ROSI. OLG. SER


A limit to renew this vessel's screwshaft expired at the end of February last, when the Third Special Survey No. 1 also became due.

On the 4th April, the Owners, who had requested that the limit might be extended to June, were informed that the same could not be extended without a further examination of the shaft. The Owners subsequently reiterated their request, but on the 14th April they were asked, through the Trieste Surveyors, to arrange for the shaft to be examined with the least possible delay.

The case again came before the Classing Committee on the 29th April, in view of the Owners' statement that the vessel would arrive at an Adriatic port early in June when the shaft would be submitted for survey.

She arrived at Trieste on the 12th ultimo, but the shaft was not submitted for survey as arranged, the Owners informing the Trieste Surveyors that it was their intention to withdraw the vessel from class.

The case again received the consideration of the Classing Committee on Friday, the 4th instant, when it was decided to give instructions for the vessel's class to be expunged from the Register Book with a red line (~~7.30~~), indicating non-compliance with the Society's Rules, and the Owners have been informed accordingly.



Lloyd's Register Foundation

10th July, 1930.

002808-002815-0208