



La correspondencia  
debe dirigirse a los  
Inspectores.

# LLOYD'S REGISTER OF SHIPPING.

UNITED WITH THE BRITISH CORPORATION REGISTER  
OFICINA PRINCIPAL: FENCHURCH STREET, 71, LONDRES, E.C.3.

Calle de Ibañez de Bilbao, 22,

Apartado de Correos No. 286, Bilbao

Telegramas: Register, Bilbao.

Teléfono: 16139

6th July, 1953.

Dear Sir,

~~Ans.~~

"CABO TORIÑANA"

With reference to your Classing Letter of  
the 3rd inst. we confirm that the plating in "L"  
sheer (starboard side aft) has been renewed.

The mean diameter of the M.P. cylinder  
for insertion in the Register Book is 759 m/m.

We regret that these items were not made  
clear in our reports.

Yours faithfully,

*Thos. S. Duffie*

The Secretary,  
LONDON.



Lloyd's Register  
Foundation

002816-002824-0150

The BILBAU Surveyors report 5,55 this ship placed in  
drydock and the requirements of Special Survey (D) for reclassification

Real time  
4/40  
Bbo 15/6  
Com. Al

5/R

CLASSIFICATION

H 12e

10.7.54.

x 12e



© 2021

Lloyd's Register  
Foundation