



La correspondencia
debe dirigirse a los
Inspectores.

LLOYD'S REGISTER OF SHIPPING.

UNITED WITH THE BRITISH CORPORATION REGISTER

OFICINA PRINCIPAL: FENCHURCH STREET, 71, LONDRES, E.C.3.

Calle de Ibañez de Bilbao, 22,

Apartado de Correos No. 286, Bilbao

Telegramas: Register, Bilbao.

Teléfono: 16139

20 APR 1953

17th April, 1953.

Ans d.

Dear Sir,

Steamer "CABO TORINANA"

With reference to your classing letter of the 6th May 1952, stating that it is concluded the equipment on the above ship will be provided in accordance with the Equipment letter "p", we have to inform you that the equipment now on board is as originally supplied for the Equipment letter "o".

We have discussed this matter with the Owners who have agreed pending the approval of the Committee, to the fitting of an additional 2 lengths of cable to bring the collective weight of the equipment on board up to that equivalent for the letter "p" and we shall be pleased if this alteration can receive the favourable consideration of the Committee in this instance.

Yours faithfully,

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

002816-002824-0154

002816-002824-0157

or remain as classed and

SP.

CLASSIFICATION

EPJ

dated 24/4/53

24 H 53

See Memo

H

*US B60 6.52 Reelamer
12.52
2.53*



© 2021

Lloyd's Register
Foundation