

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SEL'S NAME.....

Silver Star Park

Rpt.....

Yes

not

No.....

6069

6030

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Triple Expansion

If Boilers fitted with forced draught *Yes*

Tail Shaft. If fitted with a continuous liner *Yes*

If fitted with an outside gland of
approved type } *no*

The boiler headers and parts of Superheaters have been made under American Bureau Survey.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, ^{+ specification} and it is submitted she is eligible to be classed *+ Linc. 12.43.*

Fitted for oil fuel 12.43. F.P. above 150°F.

2 M.T.B. 250 lb. (Spt 230 lb)

Subject to examination of mast-head, side lights, and fore and aft gangway wiring being held before end of 12.45

YRun

30.3.44



© 2021

Lloyd's Register
Foundation

002816-002824-0296