

13017

Rpt. 14.

Port of **TRIESTE**

10th June

1946

REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs,

Having, in accordance with your instructions,
examined the Masts, Spars, Iron Work of same, and Rigging, of the
(Name of Vessel) **S.S. "ISONZO"**

on the (Date of examination) **10th June 1946**,

have to report that I found that the following repairs are required:—
gging screws of fore mast topstays to be placed in order.

in stay of foremast to renew.

remast backstays to be tightened.

the starboard shroud of foremast to renew.

forward main stay of main mast to renew.

eventor stay to main mast to renew.

funnel stays to renew (fore and after ones on port side).

re' top mast rotten for about 2 m x 10 cm for a depth of 12 cm, to renew.

Trieste, 16/10/1946:— All above repairs have been satisfactorily
carried out.

Vidulich Mare

see Lire 200.— :

to the Surveyors,

Lloyd's Register of Shipping,

TRIESTE

2m.9.29.



© 2020

Lloyd's Register
Foundation

002825-002829-0012

notation of S.S. (Dr.) Trieste 10.46 also with notation of Lloyds