

5m.7.50

1

D.B. 92 BOT

Dec 92 B

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Sct T.S. "HIRAVATI" Report Gls No. 50931

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Clasing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Clasing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1<sup>st</sup> Entry When due Revised Rules

✠ A. I. (Steel) With Ironboard for Coasting Service Bombay and Goa

1 D<sup>K</sup> 21 276 F 7 A 24  
Cell D.B. U E 18' 38t, F.P.T. 18t, A.P.T. 15t.  
F.K, 8 B.H, pt cem pt asp, Lloyds A/C.P.

Shade Deck.



© 2020  
Lloyd's Register  
Foundation

002825-002829-0166

30.10.30