

4E

6 FEB 1958

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... "COCHRANE"..... REPORT..... Lgs..... No..... 1775.

Damage due grounding. The vessel afloat. Pumping arrangements and steering gear generally examined and found in order. The main condenser examined and found in order. Chief Engineer reported satisfactory operation of the main and auxiliary machinery under working conditions, subsequent to the reported grounding.

The Surveyor recommends vessel be specially examined at the next drydocking.

IT IS SUBMITTED that this vessel is eligible to remain AS CLASSED, subject as recommended.

ADW  
31.1.58.

002838-002845-0003

© 2020

Lloyd's Register  
Foundation