

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel S.S. "Cochrane" Report Gls. No. 42555.**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry. When due \_\_\_\_\_

\* 100. A. I. (Steel)

2 Dks (Stl).

Cell DB 378' 1299t, FPT 142t, APT 40t.

FK, 7BH, Cem, Lloyds A+CP P 37; B 188; F 49!

Date of Build 3.23.

see letter  
rec 4/4/23

M

A.W.J.  
21/3/23.

It is concluded the tank top is increased in thickness in way of the hatchways as approved, but the surveyors should be requested to state if this is so.

In fls 4/4/23



© 2020

Lloyd's Register  
Foundation

002838-002845-0011