


SPARES FOR REFRIGERATING MACHINERY
CARGO PLANT ONLY.

- ✓ 1. 1" reg. valve complete. ✓
- ✓ 1. 1" reg. valve spindle. ✓
- ✓ 1. 1" stop valve complete. ✓
- ✓ 1. 1" stop valve chest. ✓
- ✓ 1. 2½" " " complete. ✓
- ✓ 1. 3½" " " " " ✓
- ✓ 1. 3½" " " chest. ✓
- ✓ 1. ¾" gauge valve complete. ✓
- ✓ 1. Set 2½" T. & G. flanges ✓
- ✓ 1. Set 3½" " " ✓
- ✓ 1. Set 1" " " ✓
- ✓ 12. 1½" Brine pipe couplings, galvd. ✓
- ✓ 6. B.C. brine thermometers. ✓
- ✓ 3. 1½" brine gate valves. ✓
- ✓ 1. Compr. cylinder cover. ✓
- ✓ 1. Stuffing box for front cover. ✓
- ✓ 1. Plug for back cover. ✓
- ✓ 2. Boxes 3/16" Kerko Packing. ✓
- ✓ 2. " ⅜" ditto. ✓
- ✓ 2. Sets Snowdon Metallic Packing. ✓
- ✓ 1. Lantern ring for compressor gland. ✓
- ✓ 1. Neck Bush " " " " ✓
- ✓ 18. Compr. valves. ✓
- ✓ 36. Compr. valve springs. ✓
- ✓ 6. Compr. valve seats. ✓
- ✓ 6. Compr. valve guards. ✓
- ✓ 3. Compr. valve cages. ✓
- ✓ 1. Compr. piston. ✓
- ✓ 1. H.P. steam piston. ✓
- ✓ 1. Set H.P. piston rings. ✓
- ✓ 1. Set L.P. piston rings. ✓
- ✓ 2. Sets Compr. piston rings. ✓
- ✓ 1. Set compr. piston rod with nuts, etc. ✓
- ✓ 1. Steam piston rod with nuts, etc. ✓
- ✓ 2. Crosshead pin bolts & nuts. ✓
- ✓ 1. Set crankpin bolts & nuts & steps. ✓
- ✓ 1. Half crankshaft. ✓
- ✓ 2. Main bearing studs & nuts & steps. ✓
- ✓ 1. 6" NH3 gauge. ✓
- ✓ 1. Pair crosshead brasses. ✓
- ✓ 1. Fitted box for rods, valves, etc. ✓
- ✓ 1. Complete set of compressor joints. ✓
- ✓ 78. Assorted Tauril joints. ✓
- ✓ 27. Assorted rubber joints. ✓
- ✓ 24. Assorted bolts and nuts. ✓
- ✓ 1. Set of 1" Ratchet screwing dies. ✓
- ✓ 1. H.P. eccentric sheave. ✓
- ✓ 1. L.P. " " " " ✓
- ✓ 1. Eccentric rod & strap. ✓



© 2020

Lloyd's Register
Foundation

SPARES FOR REFRIGERATING MACHINERY
CARGO PLANT ONLY.

- ✓ 1. Steam cylinder valve spindle, complete with nuts, etc. ✓
- ✓ 1. Piston valve for H.P. cylinder. ✓
- ✓ 1. Air pump bucket & rod. ✓
- ✓ 1. Set of valves for air pump. ✓
- ✓ 6. Steam condenser tubes. ✓
- ✓ 12. " " " ferrules for inlets. ✓
- ✓ 12. " " " ferrules for outlets. ✓
- ✓ 1. Spring for 1 $\frac{1}{4}$ " H.P. Cylr. relief valves. ✓
- ✓ 1. Spring for 1 $\frac{1}{2}$ " L.P. Cylr. ✓
- ✓ 3. Full lengths 1 $\frac{1}{2}$ " reg. bore tube (galvd.) ✓
- ✓ 3. O.G. Bends for air cooler, galvd. ✓
- ✓ 3. 1" bore NH3 bends - galvanized. ✓

SPARES FOR WATER PUMPS.

- ✓ 1. Pump bucket with rod & rings. ✓
- ✓ 1. Set of water valves & springs. ✓
- ✓ 1. Steam piston with rod & rings. ✓

SPARES FOR BRINE PUMPS.

- ✓ 1. Steam piston with rod & rings. ✓
- ✓ 1. Pump bucket with rod & rings. ✓
- ✓ 1. Set brine valves & springs. ✓

SPARES FOR FANS & MOTORS.

- 2. Grease guns for nipples on couplings.
- 1. Set springs for couplings.
- 1. D.I. fan runner.
- 1. Bearing.
- 1. Armature.
- 1. Set brushes & holders.
- 1. Set bearing bushes.
- 1. Set contacts, springs & coils.
- 2. Pilot lamp fuses.
- 1. Wooden storage box.

SPARES FOR PROVISION BRINE PUMP.

- 1. Steam Piston with rod & rings.
- 1. Brine pump bucket with rod & rings.
- 1. Set of brine pump valves & Springs.



© 2020

Lloyd's Register
Foundation