

COPY

LLOYD'S REGISTER OF SHIPPING




2720

Port YOKOHAMA
 SS/MS "GOOD HOPE"
 This Certificate 7th October, 1958
 Accompanies YOKOHAMA
 REPORT No. 2720
 Dated 7-10-58

This is to Certify that I have
 Surveyed the Machinery of the M.V. "GOOD HOPE" 6716 tons gross of
 Panama, whilst the vessel lay afloat at Kamaishi, Japan, on the 6th
 October, 1958
 and that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report stating that all recommendations made by
 me in connection therewith have been carried out to my satisfaction; also
 that I will **Recommend** that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

that her Machinery Classification Record be continued in the Book.
 subject to Main Engine No.2 journal and No.5 crank shaft forward web being
 examined by 12/58 (6 mos. limit) and to Main Engine not to exceed 90 r.p.m.
 runtime as previously recommended, and to No.2 main engine driven compressor
 cylinder Metalock repairs being specially examined by the end of December
 1958 (3 mos. limit).

Parts now examined:
 (C.S. Items only)


 Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

R. TANEDA

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS (CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS (OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:
 While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
 d, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
 or to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
 the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
 tees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

1.) 1.58 KOB /hy

002838-002845-0271

Lloyd's Register
 Foundation