

2m. 10. 83.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel Sc. "THORN"

Report

gls.

No.

54641.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry.

When due

✓

✠ 100 A. I. (Steel)

1 Dⁿ

FPT 54t, APT 39t.

BK 6", 3BH, Cem, Lloyds A+CP.

Q 81', B 7', F 20',

Machy aft.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book

X

X



© 2020

Lloyd's Register Foundation

Handwritten signatures and date: 5.7.34

002846-002852-0031