

NO RESPONSIBILITY WILL BE ACKNOWLEDGED FOR ANY CONSEQUENCES ARISING OUT OF STRIKES, LOCK-OUTS, COMBINATIONS OR OTHER LABOUR DISTURBANCES NOR FOR LOSS OR DELAY DUE TO HOLIDAYS, BAD WEATHER, FIRE, ACCIDENT OR ANY OTHER CAUSE BEYOND THE COMPANY'S CONTROL OFFERS FOR DRY DOCKING ARE SUBJECT TO DOCK BEING AT LIBERTY. ALL TRANSPORTING AT OWNERS RISK.

R. & H. GREEN AND SILLEY WEIR, LTD.

SHIP REPAIRERS & ENGINEERS.

TELEGRAMS:
REPAIRS, ALDOCK, LONDON.

TELEPHONE:
ALBERT DOCK 2121 (5 LINES)



Works:

BLACKWALL YARD: EAST 4171 & 4172	SURREY DOCKS, BERMONSEY 3187 & 3188
ROYAL ALBERT DOCK; ALBERT DOCK 1641 (3 LINES)	MILLWALL DOCK: EAST 4611 & 4612
CENTRAL WORKS ROYAL ALBERT DOCK; ALBERT DOCK 1506	TILBURY DOCK: TILBURY 53 & 113

CITY OFFICE: 130-132, LEADENHALL STREET, E.C.3.
TELEPHONE AVENUE 8308 (3 LINES) TELEGRAMS: INTERKNIT, STOCK, LONDON.

General Offices:
Royal Albert Dock,
LONDON, E.16.

2nd November 1933.

OUR REF.	GM/IR.
YOUR REF.	

Handwritten signature/initials

The Secretary,
Lloyd's Register of Shipping,
71 Fenchurch Street. E.C.3.



Dear Sir,

S/S "FORDSDALE"

We have been requested by the Owners of the above Vessel to fit cast iron chests to facilitate changing over from oil to water and vice versa in the Double-Bottom Tanks.

We have not much time in which to do this work, and we should be glad to hear if the arrangement meets with your approval as soon as possible.

Prints Nos. 15738 and 15739, in duplicate, were handed to you by our Mr. Edminson this afternoon.

Yours faithfully,

R. & H. Green and Silley Weir © 2020

 Lloyd's Register Foundation
 002846-002852-0284

Referred to the Chief Surveyor

Referred to the Chief ~~Ship~~ Surveyor

hij

[Handwritten scribble]

- 3 NOV 1933

LZ 27

J: 53 - 70 + 5LS

0-8

US-9

70 + 5LS

US-9

US-9

US-9

US-9 + 70 + 5LS



© 2020

Lloyd's Register Foundation