

1.31.

2E

ed by Chief Engineer Surveyor.

Received from Chief Engineer Surveyor

SEL'S NAME

Fordsdale

Rpt.

Low

No.

995/1

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

re of Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due *7.33* ~~held~~ *now*

~~completed~~, and the following ~~repairs~~ *alterations* carried out (due to ~~to~~ *now*) :-

new H.P. cylinders with Kentz valves fitted
Superheaters fitted to S Boilers

It is submitted the vessel is eligible to remain as classed, with notation of *B. 11-33 S 11-33* as recommended.

Amend H.P. cy. dia to 24 1/2"

[Signature]

28/11/33

© 2020



Lloyd's Register Foundation

002846-002852-0330

Note for RB H.P. cylinders 24 1/2 DIA.