

1E

of Engineer Surveyor

Received from Chief Engineer Surveyor

AME

Corfu.

Rpt.

Is.

No.

57824

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.

of Engine

*6 Steam turbines
A.P. geared to 2 screw shafts*

Boilers fitted with forced draught

Oil Shaft. If fitted with a continuous liner

If fitted with an outside gland of

approved type

*Is.
Is.
Is.*

is vessel's machinery appears to have been built in accordance
e Rules and the approved plans, and it is submitted she is

to be classed



+ Rule 9-M.

Fitted for oil fuel 9-M 7.P. above 150°F.

Boilers 425-H.

200. 230H

N. 257 7/10/34



© 2021

Lloyd's Register
Foundation