

23 SEP 1958

P/S NAME "KYLEBANK" AR. REPORT Dub. No. 8481.

standing Conditions of Class: Subject to permanent repairs to indented shell plating and frames (s.s.f) being effected by next Special Survey and to set in sheerstrake plates Nos. 2 & 3 with structure in way (p.s.f) and shell plates B.1 & 2 and C.1 (p.s.f) all being specially examined and dealt with as necessary by next Special Survey.

orsement of Certificate (As before ~~XXXXXX~~)

veys due: SPECIAL SURVEY (C) due 9,58. Postponement until 9,59 approved provided a General Examination is held as stated by Owners, the period for the postponement being determined by the condition as then found.

ure of Present Survey: (Afloat and in dry dock) General Examination

cial Features: None.

Interim Certificate in order (Yes-~~No~~-None)

ms Outstanding: (If any for S.S.) All items outstanding.

. to be completed by: See Committee Minute.

ommendation: SUBMITTED record of 'DS 8,58' be assigned as recommended, SUBJECT as above.

DS 8,58. Subject.

S.R.L. APPENDIX. Forecastle side plating (s.s) indented.

IT IS FURTHER SUBMITTED the Owners' request to postpone the S.S. until 9,59 merits the favourable consideration of the Committee.



© 2020 Lloyd's Register Foundation

Handwritten signature and date: 15/9/58