

"THEOBALDIUS"

IT IS SUBMITTED the Owners be informed in reply to their letter of the 19th instant that, to complete the Classification Survey of the machinery, the main turbine requires to be examined throughout.

In addition, the class is subject to oil gutterways being fitted in way of oil bunkers in the engine room and to the boiler blow down valve on ship's side being altered to comply with Rule requirements; also to the supply of a spare propeller and to the remaining electrical fuses of renewable type being converted to cartridge-filled type.



*Exh*

© 2020

21. 4. 49.

Lloyd's Register  
Foundation

002870-002875-0030