

Donkey Boilers
Team Pressure—
in Main Boilers 180 lb

Managers

Port Willemstad

NEWCASTLE-ON-TYNE, No 108926

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 19____

Lloyd's Register of Shipping.

(Report on Machinery, No. _____ Port 13 AUG 1951)

ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured
Lockburns Ltd. of Leamington.
The Engines or Boilers of "Rebecca" being ordered by Watts
Turichan Ltd. of London.

been inspected by me as set forth below, and found to be, so far as can
seen, sound and free from defects.

have been despatched to Smith Dock North Shields

mp Mark.

D'S TEST

00 lbs.
Iron
13/8/51

James C. Murray
Glasgow.


Two 3" C.S. Tee pieces (C.S.)
Three 1 1/2" C.S. Bends
One 4" C.S. Tee piece
Nine 1 1/2" " " " "
One 1 1/2" " " " "

are inch. 600 lbs

any. Carl-Nas 914, 59A, 858(3off) 64A, 865B(8off) 31A(2off)
232C.

spected. 13/8/51

PRINTED IN ENGLAND)



Lloyd's Register
Foundation

002870-002875-0209