

COPY

LOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

511

Port Bremen,

6th October, 1952

This is to Certify that

A. Holtz

undersigned Surveyor to this Society did at the request of

the Owners' Representative attend on board the steel sc. "JAG VIJAY",
1,100 Tons Gross, of Bombay, whilst she was lying afloat and in drydock
at the JAG Vijsenhaven on 20th August, 1952 and subsequently, for examination
of the Life Saving Appliances on board the vessel.

Of Examination found:

A.) BOATS

1. Life boat on Port Side, steel, Dimensions 30,1' x 9,55' x 4,0'

For 60 persons, built by Messrs. Mechans Ld.,
Glasgow, 1952, Patent 548867. M.O.T. 18.9.52

2. Life boat with Motor on Starbd. side, steel, Dimensions
30,0' x 9,55' x 4,0'

For 60 persons, built by Messrs. Mechans Ld.,
Glasgow, 1952
M.O.T. 18.9.52

The above new life boats and davits, supplied from U.K. have now been
fitted on board, examined including life boat equipment and launching
arrangements and were found to be complete and good and in accordance
with the applicable Requirements of the M.O.T. Rules.

B.) Life Jackets and Life Buoys

10 Life jackets of standard Kapok Type, distributed as required;
8 Circular cork life buoys (4 with lights, 2 with lines and 2
quick release) placed on bridge and weather rails, have all been
examined and were found to be satisfactory, in accordance
with M.O.T. Regulations governing Life Saving Appliances.

The above is a correct description of the Life Saving Appliances
which were found on the vessel at the time of examination.
All the Appliances appeared to be in a satisfactory condition.

See 8.8.0
Exp. nil.

A. Holtz
Surveyor to Lloyd's Register of Shipping.

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of
its or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."