

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report 26-5-59 19 When handed in at Local Office 26-5-59 19 Port of Toronto
No. in Survey held at Toronto Date, First Survey and Last Survey 11.5.59. 19
Reg. Book (No. of Visits 1)

65868 on the Steel S.S. "JAMES STEWART"

TONNAGE:- Built at Glas. By whom Napier & Miller Ltd., When 1926 4
GROSS 1760 Owners Leitch Transport Ltd.,
UNDER DK Managers J. D. Leitch
NET 1304 Port belonging to

Surveyed Afloat or in Dry Dock? afloat Name of Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 3472 Port T70

REPAIRS, OR EXAMINATION AS PER RULE FOR

LAKE annual SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
BS* Great Lakes & St Limited Gulf of St. Lawrence Service Lake SS 6/55 AS 4/58 DS 6/55	MBS* ES 6/55 M 4/58 CL 6/55 SPS 3/51

WRECK
SECTION
No. 703

ITEMS EXAMINED AND CONDITION FOUND, ETC.	
Holds including bulkheads, inner bottom plating, etc.	Good
Bilges & ceiling.	-do-
Tween decks.	-do-
Deck & deck erections.	-do-
Machinery Space.	-do-
Under Engines & Boilers.	-do-
Masts, Rigging & Outfit.	-do-
Windlass & Hawse Pipes.	-do-
Air & Sounding Pipes with closing appliances.	-do-
Pumps and Pumping arrangements outside machinery space.	-do-
Steering arrangements including gear.	-do-
W.T. Doors & Sluice valves.	-do-
Ventilator coamings with their closing appliances.	-do-
Hatchway coamings with their closing appliances.	-do-
Casings, companionways and their closing appliances.	-do-
Superstructure bulkheads with their closing appliances.	-do-
Guard rails & freeing ports.	-do-
Overboard discharges, also ash chutes & other shell openings.	-do-

	EXAMINED	TESTED	CONDITION
Peaks	Yes	No	Good
Side Tanks in hold.	/	/	
Deep Tanks			
Cargo Tanks			
Cofferdams } (Tankers)			
Pump Rooms	/	/	
Has a Load Line Annual Survey been held?			
Has a Grain Survey been held?			
Has a Damage Survey been held?			

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4.54" or "to remain as classed and to have record of docking, I.54 and the notation Lake S.S. 4.54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 5.59

Survey Fee \$ 36.00 Fees applied for,
Special Damage or Repair Fee (if any) \$ 4.00 June 3, 1959
Travelling Expenses \$ 5.00
Second Surveyor's Fee (if any) \$

Committee's Minute

Character Assigned

TUESDAY 30 JUN 1959

AS 5.59

MBS 2.59

SPS 12.56

Surveyor to Lloyd's Register of Shipping.
T. L. Millar



© 2020

Lloyd's Register
Foundation

002883-002890-0301

Noted T.L. MBS dt.

Noted
for
Header