

Ital. 52672


"Enforcer"

Before this Case receives consideration Submitted the Ital
Surveyor attention to the dynamo test sheets forwarded
with above report. One of which does not correspond
with the first entry report. These certificates should
be returned, for verification & installed in the usual
way.

X

See Ital letter 1. 1. 45

002916-002922-0087



© 2020

Lloyd's Register
Foundation