

Ship's name "BRITISH ARDOUR"Port

Gls.

No. 93997Last survey date 19.10.6

Class is subject to indented shell plating etc. E.8 and F.8  
H.11 & 14 and J.13 (p.s.) and H.13 & 14 and J.13 (s.s.) being  
specially examined and dealt with as necessary by the S.S.  
also to set in shell plates F.7 (s.s.a) and J.19 (p.s.a)  
and structure in way being specially examined and dealt  
with as necessary by the next drydocking.

ACTION is DEFERRED for S.S. by 9,62.

S.R.L. Appendix (as before ~~xxxnone~~)

Surveys due SPECIAL SURVEY (C) due 9,61. Postponement until 9,62  
approved 12.12.61.

Nature of present survey (afloat ~~and in drydock~~)

Examination afloat for voyage in tow to Antwerp.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by~~Recommendation~~SUBJECT as above.


ACTION is DEFERRED for S.S.

IN S.R.L. APPENDIX.

Indents in side shell plates  
H.5, J.5 and K.5 (p.s.f) and  
J.10 & 11 (s.s. from fwd)

NOTE:- Ship has been towed to Antwerp for breaking up.

Arrived Ant 25/10

Lloyd's Register  
Foundation  
8/11/62