

COPY

Ship's name "BRITISH ARDOUR" Port Gls. No. 93997

Last survey date 19.10.62

Class is subject to indented shell plating etc. E.8 and F.8
H.11 & 14 and J.13 (p.s.) and H.13 & 14 and J.13 (s.s.) being
specially examined and dealt with as necessary by the S.S.
also to set in shell plates F.7 (s.s.a) and J.19 (p.s.a)
and structure in way being specially examined and dealt
with as necessary by the next drydocking.

ACTION is DEFERRED for S.S. by 9.62.

S.R.L. Appendix (as before or none)

Surveys due

SPECIAL SURVEY (C) due 9.61. Postponement until 9.62
approved 12.12.61.

Nature of present survey (afloat and in drydock) xxx

Examination afloat for voyage in tow to Antwerp.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by

Recommendation xxx


SUBJECT as above.

ACTION is DEFERRED for S.S.

IN S.R.L. APPENDIX.

Indents in side shell plates
H.5, J.5 and K.5 (p.s.f) and
J.10 & 11 (s.s. from fwd)

NOTE:- Ship has been towed to Antwerp for breaking up.



Lloyd's Register
Foundation