

Lloyd's Register of British & Foreign Shipping

13, Exchange,

Plymouth, 10 June '10

LLOYDS REGISTER,
LONDON.

REC'D 13 JUN 1910

ANS'D 4
for Jul 13/6/10.

The Secretary
London
Sir

With reference to information asked for in your letter of the 7th inst. in connection with the first entry report No 5306 on the S.S. 'Daumbe II' I beg to report -

- (a) Work remaining to be done to the hull of the vessel is the top of the casing over boiler hatchway to be rivetted up when the boiler is in place, and
- (b) Tests for the bowen chain cable are Statutory 18 Tons, Breaking 27 Tons For the other chain 6 Tons 15 Cwt was noted on certificate as "Admiralty Private Test" -

I am Sir
Your obedient servant
Jas L. Lang



© 2020

Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor.

as

JUN 14 1910

The Surveyors were
informed by letter
on the 13th inst.
re completion of
Survey.

W
14.6.10

© 2020

Lloyd's Register
Foundation

