

COPY

LLOYD'S REGISTER OF SHIPPING

Port LiverpoolDate 16th September, 1960.

This is to Certify that I have

surveyed the s.s. "CLAN ALPINE", 7103 tons gross of London whilst lying
 at Birkenhead on the 12th September, 1960 and subsequently for
 repairs to defective shell riveting and frames in (p.s.) deep tank.

and that I am transmitting to the Committee of Lloyd's Register of
 Shipping, London, a Report, stating that all ^{temporary} repairs recommended by
 have been completed to my satisfaction, also that I am
 commending that she be continued as classed without record of docking,
 subject to temporary repairs to shell rivets and frames in (p.s.) deep tank
 repaired Liverpool 9,60) being specially examined and dealt with as necessary
 before the ship's departure from Hong Kong to which port she is now bound,
 to all other conditions at present attached to the ship's class being
 left with as previously recommended.

Surveyor to Lloyd's Register.

J.D. Sutherst.

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BIS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."