

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "CEDARPOOL"

Official No. 168944

Port of Registry WEST HARTLEPOOL

This ship has been under survey at DUNSTON-ON-TYNE

on 10th to 24th MAY 1956 and the following alterations to the conditions of assignment of loadlines have now been effected ~~found~~

Scuppers, wash basins and bath wastes from deckhouses above freeboard deck lead overboard above 2nd Deck now fitted with gunmetal automatic non-return valves at Ship's side - 13 valves fitted viz:-

1 - 2 $\frac{1}{2}$ " and 1 - 2" from Engineers accommodation,

2 - 2", 1 - 1 $\frac{1}{2}$ " and 1 - 1 $\frac{1}{4}$ " from Stewards accom-

modation and 3 - 2" on Port side, 3 - 2" and 1 -

1 $\frac{1}{2}$ " on Starboard side from midship accommodation.

J. H. JOHNSON.

SURVEYOR TO LLOYD'S REGISTER
NEWCASTLE-ON-TYNE

11 JUN 1956

A copy of this Report has been placed on board.