

ived by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SSSEL'S NAME

Empire Service

REPORT

Don. No. 8309
" " 8311
" " 8310
Rec. " 100,314

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Triple Expansion.

If Boilers fitted with forced draught


Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of }
 approved type

yes
yes
no

This vessel's machinery appears to have been built in accordance
 with the Rules and the approved plans, *and M.O.W.T. specifications* and it is submitted she is
 eligible to be classed *+LMC 5.42.*

L.Y.
8/6/42.



Lloyd's Register
 Foundation

003013-003017-0203