

8 NOV 1958

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME CASSIAN SEA ^{LTR.} REPORT OWNERS No. 16-7-58

(also of class(s) of 26-2-58)

Submitted copy of this letter be forwarded to London Out-don Office for their guidance. Also, that Owners be informed that in all future donkey boiler surveys, the safety valves of the oil fired donkey boilers should be adjusted by a surveyor to this Society at a convenient port after examination of the boiler, not by the ships personnel.

J.

18 JUL 1958

To complete DBS, oil burning arrangements & remote controls to be examined under working conditions.



© 2021

Lloyd's Register Foundation

003023-003028-0184