

[Thin Copy for attaching to Report.]

# LOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Port of ROTTERDAM.

**LONGS TO** 29th January, 1958.

**SHIPPING ROTTERDAM REPORT No: 44821**

a, E.C.3.

Sirs,

With reference to the Survey  
being held on the motorvessel

"CASSIAN SEA"

to inform you that, in consequence of  
condition of this vessel's governor


rd generator

it be my duty to recommend to the  
committee that the same be examined and tested  
under working condition

~~by~~ by July, 1958  
provided for in the Rules, (6 months limit)

appears on the other side:—the continuance  
vessel's character in the Society's Register  
to be subject to the due fulfilment of this  
on.

Yours faithfully,

  
Engineer Surveyor to Lloyd's Register.

D. Kampman.

Messrs. Pioneer Shipping Corp. Ltd.,  
c/o Marcou & Sons (Shipbrokers) Ltd.,  
Bevis Marks House,  
Bevis Marks,  
LONDON, E.C. 3,  
England.

003023-003028-091

Lloyd's Register  
Foundation

[Thin Copy for attaching to Report.]

[Thin Copy for attaching to Report.]

[Thin Copy]

LLOYD'S REGISTER OF SHIPPING

**LLOYD'S REGISTER OF SHIPPING**

71, Fenchurch Street, London, E.C.3.

**Extract from the Rules of the Society respecting  
Surveys of Machinery:—**

If, upon examination, it is found desirable that any piece of machinery should be again examined before the date of the next certificate for a limited period will be granted in accordance with the nature of the case.

Yours faithfully,



© 2021

Lloyd's Register  
Foundation

Pioneer  
rcou &  
Marks H  
marks,  
E.C.  
land.