

Boats *Four steel life boats*
Ceiling in Holds, thickness and material

Steering Chains, Size and Test

Cargo Battens, thickness material and spac

14 FEB 1935

(Received at London Office..... 19.....)

No. _____ Place Hamburg Germany Date Feb 12th 19 35

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and Boilers of the Vessel No. 905 building by Messrs. Deschimag Bremen for Messrs. Deutsch Amerikanische Pet. Ges.

of _____ Tons. Length 485' Breadth 69'9", Depth 37'0" intended to be Classed 100 A1 Carrying Petroleum in Bulk.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

Engine Makers Schichau

Boiler Makers _____

Signature R. L. Hague

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

The amount of Entry Fee RM : 240:00

Special Survey Fee.... RM 13666:50

by Hamburg Office
19

I am of opinion the Vessel should