

TELEGRAMS: "LLOYD'S REGISTER, ROTTERDAM"

TELEPHONE No. 25355 (2 lines)

All communications to be addressed to  
THE SURVEYORS

## Lloyd's Register of Shipping,

Reference:

S.

P.O. Box 701, Westerkade 5b, Rotterdam, 7th February 1947.

RECEIVED

10 FEB 1947

ANSO

Dear Sir,

s.s. "DUIVENDIJK".

With reference to your S letter of the 31st January instant I have to inform you that the heating surface of the superheater is not included in the figure 16140. The heating surfaces are for main boilers 1500 M<sup>2</sup> 16140 □ ft. Super heaters 690 M<sup>2</sup> = 7383 □ ft.

The thickness of the screwshaft liner is 23,5 mm and 16,5 between the bearing surfaces.

Yours faithfully,

*CHP Bounce*

The Secretary,  
LONDON.



© 2021

Lloyd's Register  
Foundation

003019-003037-0104

Referred to ~~Mr. Parks~~ <sup>D.O.</sup>

Submittal as LHP  
MS. 23523 be  
MN 1603 be  
Went in the R.B.  
9.5. 12/2/47.

For Engineer Sardewars (F.E. Rets.) to note.  
1 mls *[Signature]*




© 2021

Lloyd's Register  
Foundation

Refer

All com  
TH



TELEG

The