

Spare Electrical Parts.

- 1 - Field Coil for 600 K.W. Main Generator
- 1 - Field Coil for 75 K.W. "
- 1 - Field Coil for Propelling Motor
- 1 - Set Carbon Brushes for 600 K.W. Generator
- 1 - Set " for 75 K.W. "
- $\frac{1}{2}$  - Set (sufficient for 1 Commutator)

2-3000 HP  
205 KW

1-500 HP  
Propelling  
Motor

Carbon Brushes for Propelling Motor

- 1 - Bearing for 600 K.W. Generator
- 1 - Spare Armature for Steering Gear Motor.

Wm Gordon Macmillan  
GREENOCK.



© 2020

Lloyd's Register  
Foundation

003038-003045-0059 60