

Mr. Zulver mentioned over the telephone this morning that their specification with the Builders of this vessel required that the classification fees should be paid by the Builders, and they assumed therefore that the fees have accordingly been paid to the Society's Surveyors at Hamburg.



*AS* 2020

Lloyd's Register  
Foundation

003038-003045-0179