

Lloyd's Register of Shipping.



13, Engerstrasse,

Düsseldorf, 7th September 1934.

Order: RZ.7673.

This is to Certify that

John Stanley H e l y e r

the undersigned Surveyor to this Society did at the request of Messrs. Press- & Walzwerk A.G. of Düsseldorf-Reisholz attend their Works on the 3rd September 1934 for the purpose of inspecting and testing 194 seamless Siem. Mart. Steel plain boil.-tubes, details as below, to the order of Messrs. Howaldtswerke A.G. of Kiel and intended for the vessel No. 732.

Twenty of these tubes were, in the presence of the undersigned, tested by hydraulic pressure to 1000 lbs. per square inch and showed no signs of defect.

2% were cut up and subjected to expanding, crushing and flattening tests with satisfactory results.

PARTICULARS OF TUBES.

Number.	Length.	outs.	Diameter.	Thickness.	Description.
194	2585mm		85mm	4mm	SEAMLESS

The tubes have been inspected internally and externally.

Fees: RM 20,-
Expenses: RM 3,-
Total: RM 23,-

Fee £ : :

J.S. Helyer
Surveyor to Lloyd's Register.

Signed advice note attached.

NOTE.—As it is impracticable to mark rivets, bars or tubes of small section for subsequent identification, it must be understood that this certificate does not guarantee the identification of the rivets, bars or tubes received by the consignee or purchaser, with those from which the samples tested were taken.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."