

11 JUN 1953

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME

"GARD"

REPORT

Cpn.

No. 14249

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Transversely framed stanchion.

The COPENHAGEN Surveyors report 5,53 ship placed in drydock and girders fitted under the deck in accordance with approved plan.

Minor repairs effected.

IT IS SUBMITTED the ship is eligible to continue as classed with record of docking 5,53.

5,53 Cpn.

OFFICE NOTE.

Deck stiffened - Cpn. 5,53.



W. Murray

J.M.

ABM.
9.6.53.
[Signature]



© 2011 Lloyd's Register Foundation

003065-003074-0082