

COPY

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.3.

1st October, 1947.

Dear Sir,

I beg to acquaint you that the case of the steamer "PAN" has recently received consideration in connection with the survey carried out by the Society's Surveyors at Liverpool in July last.

As a result of this inspection a notation of 100.A1 (Classification Contemplated) 7,47 BKN. has been assigned together with records of "Examined 7,47", valid for 12 months and B.S.8,47.

The following items have been accepted as part of the vessel's Special Survey for classification:9

Hull: Internal examination of Nos.4 and 5 D.B.tanks, after peak tanks and fore and after peak spaces and the examination of hatch supports and rigging.

Machinery: Steam pipes tested
Fan engine examined
Starboard dynamo engine examined
Auxiliary condenser examined and tested
Propeller and sea connections examined.

P.T.O.

003083-003091-0145

I have to add that as it is understood that the screwshaft was renewed in June 1945 under the survey of Surveyors to the American Bureau, the next Screwshaft Survey will be considered as becoming due in June 1948.

Yours faithfully,

Clerk to the
Classification Committee.

S.Ventouris, Esq.,
Messrs. S.G. Embiricos Ltd.,
708, Bury Street,
E.C.3.



© 2020

Lloyd's Register
Foundation