

to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

SEL'S NAME S.S. J. L. Luckenbach Report Bal. No. 3395

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/02.)

of Survey S.S. 17°1 and When due \_\_\_\_\_

Re-instatement of class

Noted.

M

T.P.  
23. 3. 23

Cell D.B. 389'1831t Twelve dk tanks under E+B space 36'405t  
F.P.T. 281t A.P.T. 271t  
A+C.P. pt. asp. 8 BH to S. dk.



© 2020

Lloyd's Register  
Foundation

003124-003130-0168