

State of writing Report 15th Feb 1923 When handed in at Local Office 27th Feb 1923 Part of

A. J. L. Luckenbach


BLU-3395

Submitted the Surveyor be requested to state by cable whether the new Turbines have been constructed under special survey & to forward his report on them

Yps

L.S.

12/4/23



© 2020

Lloyd's Register
Foundation

003124-003130-0173

as not done, state for what reasons? Turn every report on vessels new join report no 22

at parts of the Bollers could not be thus thoroughly examined?