

COPY

Ship's name SS. TUNG FENG

Port

Hong Kong (9A.42)

No. 17343

Class is subject to scratch being examined Last survey date 7/11/62.

- in way of repair by 1/63 (12 months limit).

Record of TSCA 1/62 without mention.

Docking. Damage.

Machinery partly examined and found damaged.

The Surveyor states in view of cost of repairs to hull and machinery, it was decided that the ship be

broken-up and this has now started. Casualty report noted.

It is submitted no further action is necessary.

146
15/9/63



© 2020

Lloyd's Register
Foundation

003147-003513-0005