

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Screw M.S. "CRESCENCE"

Rpt.

Hul.

No. 47324

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 1101

Depth "d"

7.42

2nd Long. No. 3980

Proportions = $\frac{L}{D}$

11.8

Framing Bulb angle frames as approved
(+ Owners' increase)

Sheerstrake As approved (+ Owners' increase)

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*100A1

1 Dk.

Cell. DB 70' 87t, PPT 23t, APT 15t

FK, 3 BH, Cem., Lloyd's A & CP.

P 34', F 12'

Machy. aft.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book

Handwritten signature
3.11.36

Handwritten signature



© 2020

Lloyd's Register
Foundation

003147-003153-0064