

**LLOYD'S REGISTER OF SHIPPING  
17 BATTERY PLACE****NEW YORK 4, N. Y.**

COPY FOR REPORT

June 23, 1948

James Findlay, Esq.

GALVESTON

Dear Mr. Findlay:

"TOMOGERUS"

Your hull reports No. 4981 covering the Classification Survey on the above named vessel have now been examined in this office.

For your information the equipment letter of this vessel is g 7, which requires 300 fathoms of chain cable. This accordingly alters the subject placed against the vessel and your records should be altered to suit.

The watertight bulkhead 25-31 is not a rule bulkhead and the watertight doors as originally fitted could be recommended for acceptance by the Committee, but I would be pleased to have your agreement on this point.

It is not clear whether the bottom shell strapping has been fitted in accordance with the approved plan, that is, 40.8 lbs. plating, and I would be glad to have your confirmation that this has been done.

Yours very truly,

Principal Surveyor

JT/G



© 2020

Lloyd's Register  
Foundation

003147-003153-0200