

10 AUG 1961 ^{4E}

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

ME..... "KORSHOLMA"..... REPORT..... ANT..... No. 36898.

CLASS IS SUBJECT TO:

- (1) Starboard screwshaft cone being specially examined at the next dry docking.
- (2) Starboard screwshaft liner being renewed at the next dry docking.
- (3) Starboard propeller being further moved up the screwshaft taper to suit rubber-ring at the next dry docking.
- (4) Port propeller being re-conditioned or renewed at the next dry docking.

DBS due 6.61. Partly held now.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of DBS 7.61 when the survey has been completed as per this report subject as above.

JH

9.8.61.



© 2020

Lloyd's Register
Foundation

003154-003161-0053