

16 FEB 1960

Received from Chief Ship Surveyor

(a) Kel. No. 2469

P'S NAME "NEOTHYRIS"

REPORTs (b) Rot. No. 48749

standing Conditions of Class: SUBJECT to indented shell plating etc.
(p & s) being specially examined and dealt with as necessary
by the Special Survey.

L. Appendix. (As before ~~of None~~)

ure of Present Survey: (Afloat ~~and in dry dock~~)

- (a) Deferred repairs to collision damage.
- (b) Temporary repairs to (a) above.

mmendation:

SUBJECT as above, and to set in shell plating in
way of No. 1 tank, cofferdam, deep tank and
forward hold (s.s.) being specially examined
and dealt with as necessary next drydocking.

As Now. Subject

IN S.R.L. / APPENDIX.
Rudder head twisted 5°.



© 2020

Lloyd's Register
Foundation