

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report..... 19... When handed in at Local Office..... 19... Port of London

No. in Survey held at
Reg. Book. 80352 on the Wood, Iron or Steel Twin S.

Date, First Survey "NIKOLAI EJOF" (No. of Visits)
Last Survey W 19 19... MONTH 6

TONNAGE— Built at Newcastle By whom Swan, Hunter & Wigham
GROSS 9180 Owners U. S. S. R. Owners' Address Richardson, Ltd.
UNDER DE. 6697 Managers Port belonging to Vladivostok
NET 5460

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

S.B.—All alterations in the existing records should be underlined.

Last Report, No. 14024 Port Ams

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard
painted on Ship

Was a damage report made by anyone else? If so, by whom

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Feet.)
Decks	State if Tanks now tested	Dbing. Plates under Sounding Pipes	When put on, Month Year
Shaulking of Decks	Bulkheads	Engine Room Skylights	Boats
Coamings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained (State if wedges removed)
Outside Plating	Rudder	Scuppers	Sails
" " in way of sidelights	Steering gear and its connections	Cargo Hatchways	Equipment letter
Breasthooks	Windlass	Hatches of Wood Vessels	Anchors, No. of
Transoms	Have pumps now been examined and found efficient?	Planking	Chain Locker
Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Cables (State if now ranged)
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" length mean diamr. (on board) size
Longitudinals		Breasthooks & Stems ditto	Hawser & Warps
Transverses		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Floors		Timbers of Frame at openings ditto	
Keelsons		Ditto Ditto at other places ditto	
Stringers	Have Ventilators and their Coamings been examined and found efficient?	Stringers, Clamps & Shells ditto	
Inner Bottom Plating		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 2, 4," or "to remain as classed and to have record of survey, 1, 2, 4, and the notations of "No. 1-24."


Survey Fee (per Section 20) £
Special Damage or Repair Fee (if any) (per Sec. 20) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Fees applied for,
19
Received by me,
19

Surveyor to Lloyd's Register of Shipping

Committee's Minute

Character Assigned



Lloyd's Register
Foundation